

Radiation (Council Decisions) Notice 2005 (No 5)

Notifiable Instrument NI2005-336

made under the

Radiation Act 1983, s 73 (1) Notification of decisions

1 Name of instrument

This instrument is the Radiation (Council Decisions) Notice 2005 (No 5).

2 Commencement

This instrument commences on the day after notification.

3 Notice of Decisions

The particulars of decisions of the Radiation Council are as stated in the schedule.

4 Right of Review

Any persons whose interests are adversely affected by these decisions may apply to the ACT Administrative Appeals Tribunal to have the decision reviewed. Write within 28 days explaining the details of the decision and the reasons for asking for a review. To lodge an application there is a fee. You may apply to have the fee waived on the grounds of hardship. No fee is payable if you are receiving legal assistance. The Tribunal is located on the 4th Floor, Canberra House, 40 Marcus Clarke Street, Canberra City, GPO Box 9955, Canberra ACT 2601, Telephone (02) 6243 4611, Facsimile (02) 6247 0962, Document Exchange DX 5727. The Tribunal is an independent body. The Tribunal can agree with, change or reject to the original decision, substitute its own decision or send the matter back to the decision maker for reconsideration in accordance with Tribunal recommendations.

5 Reasons

If you wish to obtain a statement of reasons to explain why the decision was made you should write within 28 days of this notice to the ACT Radiation Council, GPO Box 825, Canberra ACT 2601.

6 Access to documents

You may apply for access to any documents relevant to this decision under the ACT *Freedom of Information Act 1989*. For more information contact the Freedom of Information Officer, ACT Health, telephone (02) 620 51340.

Anthony Agostino
Chairperson Radiation Council
14 September 2005

SCHEDULE

GRANTING of a LICENCE (s 73(1)(c))

With conditions

Licensee Address	Dr Rajeev JYOTI Medical Imaging The Canberra Hospital Yamba Drive GARRAN ACT 2605
Authorised Activities: Conditions	use, cause or permit to use, irradiating apparatus Diagnostic radiology. You are required to enter the total radiation exposure time of each fluoroscopic procedure into the patient's record.
Licensee Address	Dr Brendan Klar John James Memorial Hospital Strickland Cres, DEAKIN ACT 2600 The Canberra Hospital Yamba Drive, GARRAN ACT 2605
Authorised Activities: Conditions	use, cause or permit to use, irradiating apparatus Diagnostic medical radiography.
Licensee Address	Leo John Nouwens ACT wide
Authorised Activities: Conditions	use, irradiating apparatus * Use of irradiating apparatus is limited to servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.
Licensee Address	Sivarami Reddy MEKA ACT wide
Authorised Activities: Conditions	use, irradiating apparatus * Use of irradiating apparatus is limited to servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.
Licensee Address	Matthew Adams ACT wide
Authorised Activities: Conditions	use, irradiating apparatus * Use of irradiating apparatus is limited to servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.

VARIATION of CONDITION SPECIFIED in a LICENCE

(s 73(1)(d))

Include "Reason"

Reason	Address now shows location of practice
Licensee	Amanda McKeon
Address	Unit 6 10 Kennedy Street KINGSTON ACT 2604
Authorised Activities: Conditions	own or have in possession, use, irradiating apparatus Diagnostic dental radiography
Reason	Address now shows location of practice
Licensee	Janine M Mylonas
Address	Evatt Dental Care Medical Centre McClure Place EVATT ACT 2617
Authorised Activities: Conditions	use, cause or permit to use, irradiating apparatus Diagnostic dental radiography.
Reason	Address now shows location of practice
Reason	Amended conditions to licence
Licensee	Stephen Eden
Address	ACT wide
Authorised Activities: Conditions	use, irradiating apparatus Installation and servicing of irradiating apparatus. * Use of irradiating apparatus is limited to servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.
Reason	Address now shows location of practice
Licensee	Honeywell Ltd
Address	ACT wide
Authorised Activities: Conditions	sell, purchase, own or have in possession, use, irradiating apparatus Purchasing and sale of smoke detector units, each containing 37kBq of Am-241.
Reason	Address now shows location of practice
Licensee	S J O'Connor
Address	Canberra Specialists Centre DEAKIN John James Hospital DEAKIN The Canberra Hospital GARRAN National Capital Private Hospital GARRAN
Authorised Activities: Conditions	use, irradiating apparatus Use of irradiating apparatus for diagnostic medical purposes. Restricted to fluoroscopy directly related to cardiology. This licence does not permit the supervision or direction of any other person in the use of fluoroscopy except a registrar in your specialty. You are required to enter the total radiation exposure time of each fluoroscopic procedure into the patient's record.

Reason Address now shows location of practice
Licensee Leonard John Staggs
Address ACT wide
Authorised Activities: sell, use, irradiating apparatus
Conditions * Use of irradiating apparatus is limited to demonstration, servicing, maintenance and installation.
* Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT, and also with details of each sale/hire of irradiating apparatus (includes sealed radioactive sources) to an ACT based client.
Nil returns are also required.

Reason Address now shows location of practice
Reason Amended owners name
Licensee Dr Chris P. Hardwicke
Address Suite 13
Corinna Chambers
Corinna Street
WODEN ACT 2606
Authorised Activities: own or have in possession, use, cause or permit to use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Nicolaos Gondzioulis
Address Woden Chiropractic
2/48 Corinna Street
WODEN ACT 2606
Authorised Activities: own or have in possession, use, irradiating apparatus
Conditions Diagnostic chiropractic radiography of the spine, the extremities distal to and including the elbow and knee, and the A.P. view of hip and shoulder.

Reason Address now shows location of practice
Licensee D W S Davies
Address Suite 301 Colonial Mutual Building
Darwin Place
CANBERRA CITY ACT 2601
Authorised Activities: own or have in possession, use, cause or permit to use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Maurice J Mulcahy
Address National Capital Private Hospital GARRAN
The Canberra Hospital GARRAN
John James Memorial Hospital DEAKIN
Calvary Hospital BRUCE
Authorised Activities: use, irradiating apparatus
Conditions Use of irradiating apparatus for diagnostic medical purposes. Restricted to fluoroscopy directly related to urology. This licence does not permit the supervision or direction of any other person in the use of fluoroscopy except a registrar in your specialty. You are required to enter the total radiation exposure time of each fluoroscopic procedure into the patient's record.

Reason	Address now shows location of practice
Licensee	Marc David Pilkington
Address	111 Clive Steele Avenue MONASH ACT 2904
Authorised Activities: Conditions	use, irradiating apparatus Veterinary radiography.
Reason	Address now shows location of practice
Licensee	Felix S K S Tan
Address	Suite 1005, 10th Floor AMP Building Hobart Place CANBERRA ACT 2601
Authorised Activities: Conditions	own or have in possession, use, cause or permit to use, irradiating apparatus Diagnostic dental radiography.
Reason	Address now shows location of practice
Licensee	Mark A Taylor
Address	1st Floor 2 Geils Court DEAKIN ACT 2600
Authorised Activities: Conditions	own or have in possession, use, cause or permit to use, irradiating apparatus Diagnostic dental radiography.
Reason	Amended conditions to licence
Reason	Address now shows location of practice
Licensee	Diagnostic Technology
Address	ACT wide
Authorised Activities: Conditions	sell, unsealed radioactive materials Sale of I-125 radioimmunoassay kits. Council must be provided on a quarterly basis with details of each sale of a radioimmunoassay kit to an ACT based client. Nil returns are also required.
Reason	Amended activities to licence
Reason	Amended owners name
Reason	Address now shows location of practice
Licensee	James Lee Baxter
Address	ACT wide
Authorised Activities: Conditions	use, cause or permit to use, irradiating apparatus Operation and supervision of soil density/moisture gauges.
Reason	Address now shows location of practice
Licensee	Dr Anthony Dawson
Address	Suite 9 Lidia Perin Medical Centre 12 Napier Close DEAKIN ACT 2600
Authorised Activities: Conditions	own or have in possession, use, cause or permit to use, irradiating apparatus Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Robert John Boxall
Address Belconnen Animal Hospital
1 Belconnen Way
WEETANGERA ACT 2614
Authorised Activities: own or have in possession, use, cause or permit to use, irradiating apparatus
Conditions Veterinary radiography.

Reason Amended conditions to licence
Reason Address now shows location of practice
Licensee James Mackay
Address ACT wide
Authorised Activities: sell, use, irradiating apparatus
Conditions The sale, installation, maintenance, servicing and testing of medical x-ray equipment.
* Use of irradiating apparatus is limited to servicing, maintenance and installation.
* Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT.
Nil returns are also required.

Reason Address now shows location of practice
Licensee Dr Zoran Markovski
Address Tuggeranong Square Dental Surgery
Anketell Street
TUGGERANONG ACT 2900
Authorised Activities: own or have in possession, use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Nitin Gupte
Address 45 Hall Street
LYNEHAM ACT 2602
Authorised Activities: own or have in possession, use, cause or permit to use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Dr Bryan Ashman
Address ACT wide
Authorised Activities: use, irradiating apparatus
Conditions Use of irradiating apparatus for diagnostic medical purposes.
Restricted to fluoroscopy directly related to orthopaedic surgery.
This licence does not permit the supervision or direction of any other person in the use of fluoroscopy except a registrar in your specialty.
You are required to enter the total radiation exposure time of each fluoroscopic procedure into the patient's record.

Reason Address now shows location of practice
Reason Amended conditions to licence
Licensee Stuart Walkley
Address ACT wide
Authorised Activities: use, irradiating apparatus
Conditions * Use of irradiating apparatus is limited to servicing, maintenance and installation.
* Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT.
Nil returns are also required.

Reason	Address now shows location of practice
Licensee	Robert Waites
Address	Modern Dentistry Level 1, City Walk Centre City Walk CANBERRA CITY ACT 2601
Authorised Activities:	use, irradiating apparatus
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Reason	Amended conditions to licence
Reason	Amended activities to licence
Licensee	Gino Pomella
Address	ACT wide
Authorised Activities:	sell, let on hire, use, unsealed radioactive materials, irradiating apparatus
Conditions	Ni-63 Detection of explosive materials. * Use of irradiating apparatus is limited to demonstration, servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT, and also with details of each sale/hire of irradiating apparatus (includes sealed radioactive sources) to an ACT based client. Nil returns are also required.
Reason	Address now shows location of practice
Licensee	Terry Tolhurst
Address	ACT Wide
Authorised Activities:	use, irradiating apparatus
Conditions	* Use of irradiating apparatus is limited to servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.
Reason	Address now shows location of practice
Reason	Amended conditions to licence
Licensee	Brendan Hill
Address	The Canberra Hospital Yamba Drive GARRAN ACT Breast Screen (ACT Health) Cnr Moore & Alinga Sts CANBERRA
Authorised Activities:	use, cause or permit to use, unsealed radioactive materials, irradiating apparatus
Conditions	As Chief Hospital Physicist - Supervision of medical uses of: * Diagnostic x-ray equipment. * Sealed radioactive sources: Ir-192, Cs-137, Co-57, Ba-133, Sr-90. * Unsealed radioactive materials: Tc-99m, Ga-67, Tl-201, Mo-99, I-125, Cr-51, Se-75, In-111, I-131, Y-90, P-32, H-3, C-14, P-33. *Radiation therapy x-ray & electron equipment.
Reason	Amended owners name
Licensee	Canberra Clinical School, TCH
Address	Canberra Clinical School Level 5, 6 Building 10 The Canberra Hospital, Garran
Authorised Activities:	purchase, own or have in possession, unsealed radioactive materials
Conditions	Laboratory techniques (DNA labelling) using P-32, P-33. Research using I-125, H-3, C-14, Cr-51

Reason	Address now shows location of practice
Licensee	Ian Thomas Brown
Address	Chisholm Dental Surgery 72 Halley Street CHISHOLM ACT 2905
Authorised Activities: Conditions	use, irradiating apparatus Diagnostic dental radiography.
Reason	Amended conditions to licence
Reason	Address now shows location of practice
Licensee	Paul Anderson
Address	ACT wide
Authorised Activities: Conditions	use, irradiating apparatus * Installation, maintenance, servicing and testing of irradiating apparatus. * Use of sealed sources: Ir-192, Cs-137 and P-32. * Use of irradiating apparatus is limited to servicing, maintenance and installation. * Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.
Reason	Address now shows location of practice
Licensee	Lulu Ihsheish
Address	Suite 7A, DMA Professional Offices 55 Lathlain Street BELCONNEN ACT 2617
Authorised Activities: Conditions	use, irradiating apparatus Diagnostic dental radiography.
Reason	Amended owners name
Reason	Address now shows location of practice
Licensee	ATX Medical Solutions
Address	ACT wide
Authorised Activities: Conditions	sell, irradiating apparatus Sale of irradiating apparatus. Council must be provided on a quarterly basis with details of each sale of irradiating apparatus (includes sealed radioactive sources) to an ACT based client. Nil returns are also required.
Reason	Amended activities to licence
Licensee	Liang Liang
Address	Unit 5 71 Leichhardt Street Kingston Warehouse Kingston ACT 2604
Authorised Activities: Conditions	own or have in possession, use, cause or permit to use, irradiating apparatus Diagnostic dental radiography.

Reason Amended activities to licence
Licensee Serena Tan
Address Unit 5
71 Leichhardt Street
Kingston Warehouse
Kingston ACT 2604
Authorised Activities: own or have in possession, use, cause or permit to use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Jacqueline Kearslake
Address ACT wide
Authorised Activities: use, cause or permit to use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Kai Huen
Address Dickson Park Professional Centre
Cnr Antill & Cowper Streets
DICKSON ACT 2602
Authorised Activities: use, irradiating apparatus
Conditions Diagnostic dental radiography.

Reason Address now shows location of practice
Licensee Ebar Hamood
Address Dickson Park Professional Centre
Cnr Cowper & Antill Sts DICKSON 2602
Suite 2 Deakin Chambers, Hannah Pl
DEAKIN ACT 2600
Authorised Activities: use, irradiating apparatus
Conditions Diagnostic dental radiography.

REGISTRATION of an IRRADIATING APPARATUS (s 73(1)(e))

Owner Medical Imaging Department TCH
Description GE X-ray machine. Model AMX4 Plus Model 2185226 tube.
Serial Nos. 996287WK9, 2222709.
125 kVp, 320 mA.
Location Asset No. 21518
Mobile Radiography Unit
Medical Imaging Department
GARRAN ACT 2605
Conditions Diagnostic radiography.

Owner Medical Imaging Department TCH
Description Philips X-ray machine. Model Optimus.
Serial Nos. SN 0500286, SN 05001686.
150kVp, 333 mA.
Location Room 5
Medical Imaging Department
Building 12, Canberra Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Owner	ACT Health Dental Health Program
Description	Trophy Elitys x-ray machine Serial No. SLX1202 60/70 kVp, 1.07 mA.
Location	Room 6 Dental Clinic 1st Floor, Health Building 1 Moore Street CANBERRA CITY ACT 2601
Conditions	Diagnostic dental radiography.

**APPROVAL for an ALTERATION or MODIFICATION of a REGISTERED
IRRADIATING APPARATUS (s 73(1)(f))**

Include "Reason"

Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Philips Densomat digital ET dental x-ray machine with Oralix 65S tube. S/Nos 8620348, 8600563 65kVp, 7.5mA
Location	Room 1, Dental Clinic 1st Floor, Health Building 1 Moore St, Canberra City
Conditions	Diagnostic dental radiography.

Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Dental x-ray unit Trophy model CCS timer (DG073) S/No 3840 with model 708 tube S/No 3840G4275. 70kVp, 8mA
Location	Room 5 Belconnen Health Centre Benjamin Way, Belconnen
Conditions	Diagnostic dental radiography.

Reason	Amended owners name
Owner	Packianathan RAYAPPU
Description	Dental x-ray machine, Yoshida model Panpas 601 with Toshiba D-081 tube S/Nos 2L037, 2L18909. 60kVp, 10mA
Location	Room 1 Unit 2 Weetangera Shopping Centre Weetangera Place WEETANGERA ACT 2614
Conditions	Diagnostic dental radiography.

Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Dental x-ray machine, Trophy model CCX AD33 with model 708 tube S/Nos E941131, G7307 5588. 70kVp, 8mA
Location	Room 6, Dental Section Tuggeranong Health Centre Anketell Street, Greenway
Conditions	Diagnostic dental radiography.

Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Dental x-ray machine, Trophy model CCX AD 33 with model 708 tube S/Nos E930006, G7310 552. 70kVp, 8mA
Location	Room 5 Dental Section Tuggeranong Health Centre Anketell St Tuggeranong
Conditions	Diagnostic dental radiography
Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Dental x-ray machine, Trophy model CCX AD33 control with model 708 tube S/Nos 5930003, G7216 5420. 70kVp, 8mA
Location	Room 4 Dental Section Tuggeranong Health Centre Anketell St Tuggeranong
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	Radiation Oncology Department TCH
Description	Amersham Gamma Instrument Calibrator model 773, S/No 450 Cs-137, 149.1mCi(13/03/92)
Location	Physics Store Room 3.3.352 Radiation Oncology Department The Canberra Hospital, Yamba Drive GARRAN ACT 2605
Conditions	Calibration of radiation monitors.
Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Philips Densomat dental x-ray machine with Oralix 65S tube S/Nos 8923223, 9000623. 65kVp, 7.5mA
Location	Room 2, Dental Clinic Belconnen Health Centre Benjamin Way BELCONNEN ACT 2617
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Trophy dental x-ray machine model CCX with model 708 tube S/Nos G7552, 300447. 70kVp, 8mA
Location	Room 5, Dental Clinic 1st Floor, Health Building 1 Moore St, Canberra City ACT
Conditions	Diagnostic dental radiography.

Reason	Amended owners name
Owner	Nicolaos Gondzioulis
Description	Bennett X-ray Technologies Model HFQ300SE with Eureka model RAD8 tube S/Nos BHF20720, AO53067. 125kVp, 150mA
Location	Woden Chiropractic Unit 2 Gadad Chambers 48 Corinna Street WODEN ACT 2606
Conditions	Diagnostic radiography.
Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Philips Densomat dental x-ray machine with Oralix 65S tube S/Nos 8923222, 9000624. 65kVp, 7.5mA
Location	Room 3 Child & Youth Dental Therapy Belconnen Health Centre Benjamin Way, Belconnen
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Philips Densomat Digital ET dental x-ray machine with Oralix 65S tube S/Nos 9254026, 920225. 65kVp, 7.5mA
Location	Room 9, Dental Clinic 1st Floor, Health Building 1 Moore St, Canberra City ACT
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	ACT Health, Dental Health Program
Description	Gendex Densomat Dental x-ray machine. with Oralix 65s tube S/nos 9420965, 9401020. 65kVp, 7.5mA
Location	Room 3, Dental Clinic 1st Floor, Health Building 1 Moore St, Canberra City ACT
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	Medical Imaging Department, TCH
Description	Diagnostic mobile Fluoroscopy II / Radiography machine Philips model BV300 with 989601000581 tube S/Nos 3390080/000278, 3375490/000393. 110kVp, 3.1mA
Location	Mobile Fluoroscopy II (BV300) Operating Theatre Suite Lvl 3, Building 12, Canberra Hospital GARRAN ACT 2605
Conditions	Diagnostic radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Diagnostic Fluoroscopy II x-ray machine (undertable tube)
Toshiba model DC-60G s/no B8572128
Tube model A192, S/no H58141
125 kVp 160mA
Location Room 3 (Screening unit)
Medical Imaging Department
Lvl 2, Building 12, Canberra Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Siemens diagnostic (mammography) x-ray machine model
6438 506X041E with Mammomat 3000 tube
S/Nos 0140S11, 2671S20L. 35kVp, 180mA
Location Mammography Room
Medical Imaging Department
Lvl 2, Blding 12, Canberra Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Diagnostic x-ray machine (Overtable tube)
Toshiba model KXO60G, S/No B8572128, with
Varian B130 tube S/No H58488.
125 kVp, 4mA
Location Room 3 (Overtable tube)
Medical Imaging Department
Lvl 2, Blding 12, The Canberra Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with Oralix
AC tube S/Nos 811614, 851930 65kVp, 7.5mA
Location Room 1
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with Oralix
AC tube S/Nos 811612, 851931. 65kVp 7.5mA
Location Room 2
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with Oralix
AC tube S/Nos 811613, 831932. 65kVp 7.5mA
Location Room 3
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with Oralix
AC tube S/Nos 811523, 851722. 65kVp 7.5mA
Location Room 4
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with Oralix
AC tube S/Nos 811518, 851717. 65kVp, 7.5mA
Location Room 5
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with Oralix
AC tube S/Nos 811520, 851719. 65kVp 7.5mA
Location Room 6
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with
Oralix AC tube S/Nos 811519, 851718.
65kVp 7.5mA
Location Room 7
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with
Oralix AC tube 65kVp 7.5mA
S/Nos 811610, 950704
Location Room 8
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat Dental x-ray machine with Oralix 65S Tube.
S/Nos 811610, 950704
65kVp 7.5mA
Location Room 8
Dental Services Clinic,
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat dental x-ray machine with
Oralix AC tube S/Nos 811611, 851930.
65kVp 7.5mA
Location Room 9
Dental Services Clinic
Phillip Health Centre
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Diagnostic Mobile Radiography x-ray machine
Siemens Mobillett Plus HP with model P135/30R tube
S/Nos 30088S11, 03178S11.
133kVp, 450mA
Location Mobile radiography machine,
Medical Imaging Suite
The National Capital Private Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex Densomat Dental x-ray machine with Oralix 65S tube.
S/Nos 710075, 750526 65kVp 7.5mA.
Location Room 4, Dental Clinic
1st Floor, Health Building
1 Moore St, Canberra City ACT
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner Radiation Oncology Department, TCH
Description Varian model 2100CD wave guide linear
accelerator (18MeV photons, 20MeV electrons)
S/No 1494. (LINAC #1)
Location Liniac #1
Radiation Oncology Department
The Canberra Hospital, Yamba Drive
GARRAN ACT 2605
Conditions Therapeutic irradiation.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex model 765DC dental x-ray machine with
model GX70-10DC tube - 65kVp, 7mA
S/Nos 11-1507748DP, 2881, 10-1507979DP
Location Room 3, Dental Section
Tuggeranong Health Centre
Anketell Street, Greenway
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex model 765DC dental x-ray machine with
model GX70-10DC tube - 65kVp, 7mA
S/Nos 11-1507778DP, 2873, 10-150820DP
Location Room 2, Dental Section
Tuggeranong Health Centre
Anketell Street, Greenway
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex model 765DC dental x-ray machine with
model GX70-10DC tube - 65kVp, 7mA
S/Nos 11-1507797DP, 2879, 10-1508041DP
Location Room 1, Dental Section
Tuggeranong Health Centre
Anketell Street, Greenway
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Philips Medical Systems Optimus 80 x-ray machine with SRO 33100/ROT 350
HHS tube 150kVp, 1100mA
S/Nos 0203148, 84386-961859, 981859
Location A & E X-Ray Room (Assett 20916)
Medical Imaging Department
The Canberra Hospital, Garran
Conditions Diagnostic radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Toshiba TSX 101A helical CT scanner with CXXG-008A generator
S/Nos. A3522076 (system), A3522715 (generator).
Varian CXB-750D Tube Sn. 32875-5Q.
Location CT Room (Asset number 20854)
Medical Imaging Department
The Canberra Hospital, Garran
Conditions Diagnostic radiography.

Reason Amended owners name
Owner Radiation Oncology Department, TCH
Description Phillips model ACQSIM-CT Helical Scanner
Simulator S/No 3110 Generator 362250, Tube
type CTR1793RGQ S/No 13104 140kVp, 400mA
Location CT Planning Room (3.1.343)
Building 3, Level 1
Radiation Oncology Department
The Canberra Hospital, Garran
Conditions Diagnostic radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex 765DC dental x-ray machine with
Gendex-GX70-10DC tube 65kVp, 7 mA
S/Nos 15-155414133DP
Location Room 4
Belconnen Health Centre
Benjamin Way, Belconnen
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex-765DC dental x-ray machine with
Gendex-GX70-10-DC tube. S/Nos 15-646710DP,
11514, 10-1645448DP. 65kVp, 7.5 mA
Location Room 6
Belconnen Health Centre
Benjamin Way, Belconnen
Conditions Diagnostic dental radiography.

Reason Amended owners name
Owner Medical Imaging Department, TCH
Description Diagnostic mobile x-ray machine GE
model AMX4 Plus with model 2185226 tube.
S/Nos 300060-174003, 2781BC6.
125kVp 320 mAs
Location Mobile radiography unit
Medical Imaging Department
Lvl 2, Building 12, Canberra Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Reason Amended owners name
Owner ACT Health, Dental Health Program
Description Gendex 765DC dental x-ray machine with Gendex
GX-70-10 tube. S/Nos 15-1667965DP,
10-1667539. 65kVp 7.5mA
Location Room 7, Dental Clinic
1st Floor, Health Building
1 Moore St, Canberra City
Conditions Diagnostic dental radiography.

Reason	Amended owners name
Owner	Dickson Dental TLC
Description	Sirona Heliodont DS dental x-ray machine S/nos 17697,19307 with Heliodont SR 60/70/L tube S/Nos 124969, 304784. 60kVp 7mA
Location	Room 2 Dickson Dental TLC 5/30-36 Woolley Street, DICKSON ACT 2602
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	Dr Felix SKS Tan
Description	Gendex model 765DC dental x-ray machine with model GX70-10DC tube S/Nos 11-11480035,1246, 10-1483336DP. 65kVp, 7mA
Location	Room 1 Suite 1005, AMP Building Hobart Place, CANBERRA CITY ACT 2601
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	Dr Bruce Litchfield
Description	Trophy model Elitys TR-1 dental x-ray machine, S/No 9922J0030, with Trophy TRX 708 tube s/nos XBNG040, 921060 70/60kVp, 4/7mA
Location	Ground Floor Majura Medical Centre Antill & Cowper Streets DICKSON ACT 2602
Conditions	Diagnostic dental radiography.
Reason	Amended owners name
Owner	Dr Newton J Small
Description	Diagnostic x-ray unit Universal Uni-master 325/3500 UX 50H 40M S/Nos LM1588- 0981, 65819/77414. 125kVp, 300mA
Location	10 Upper Level Kambah Shopping Village Primer Court KAMBAH ACT 2902
Conditions	Diagnostic chiropractic radiography.

**APPROVAL for an ALTERATION in the LOCATION, INSTALLATION or SHIELDING of
a REGISTERED IRRADIATING APPARATUS (s 73(1)(g))**

Include "Reason"

Reason	Address now shows location of practice
Owner	Packianathan RAYAPPU
Description	Dental x-ray machine, Yoshida model Panpas 601 with Toshiba D-081 tube S/Nos 2L037, 2L18909. 60kVp, 10mA
Location	Room 1 Unit 2 Weetangera Shopping Centre Weetangera Place WEETANGERA ACT 2614
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Radiation Oncology Department TCH
Description	Amersham Gamma Instrument Calibrator model 773, S/No 450 Cs-137, 149.1mCi(13/03/92)
Location	Physics Store Room 3.3.352 Radiation Oncology Department The Canberra Hospital, Yamba Drive GARRAN ACT 2605
Conditions	Calibration of radiation monitors.
Reason	Address now shows location of practice
Owner	Medical Imaging Department, TCH
Description	Diagnostic mobile Fluoroscopy II / Radiography machine Philips model BV300 with 989601000581 tube S/Nos 3390080/000278, 3375490/000393. 110kVp, 3.1mA
Location	Mobile Fluoroscopy II (BV300) Operating Theatre Suite Lvl 3, Building 12, Canberra Hospital GARRAN ACT 2605
Conditions	Diagnostic radiography.
Reason	Address now shows location of practice
Owner	Medical Imaging Department, TCH
Description	Diagnostic Fluoroscopy II x-ray machine (undertable tube) Toshiba model DC-60G s/no B8572128 Tube model A192, S/no H58141 125 kVp 160mA
Location	Room 3 (Screening unit) Medical Imaging Department Lvl 2, Building 12, Canberra Hospital GARRAN ACT 2605
Conditions	Diagnostic radiography.

Reason	Address now shows location of practice
Owner	Medical Imaging Department, TCH
Description	Siemens diagnostic (mammography) x-ray machine model 6438 506X041E with Mammomat 3000 tube S/Nos 0140S11, 2671S20L. 35kVp, 180mA
Location	Mammography Room Medical Imaging Department Lvl 2, Blding 12, Canberra Hospital GARRAN ACT 2605
Conditions	Diagnostic radiography.
Reason	Address now shows location of practice
Owner	Medical Imaging Department, TCH
Description	Diagnostic x-ray machine (Overtable tube) Toshiba model KXO60G, S/No B8572128, with Varian B130 tube S/No H58488. 125 kVp, 4mA
Location	Room 3 (Overtable tube) Medical Imaging Department Lvl 2, Blding 12, The Canberra Hospital GARRAN ACT 2605
Conditions	Diagnostic radiography.
Reason	Address now shows location of practice
Owner	Radiation Oncology Department, TCH
Description	Varian model 2100CD wave guide linear accelerator (18MV photons, 20MeV photons) S/No 1494. (LINAC #1)
Location	Linac #1 Radiation Oncology Department The Canberra Hospital, Yamba Drive GARRAN ACT 2605
Conditions	Therapeutic irradiation.
Reason	Address now shows location of practice
Owner	Medical Imaging Department, TCH
Description	Philips Medical Systems Optimus 80 x-ray machine with SRO 33100/ROT 350 HHS tube 150kVp, 1100mA S/Nos 0203148, 84386-961859, 981859
Location	A & E X-Ray Room (Assett 20916) Medical Imaging Department The Canberra Hospital, Garran
Conditions	Diagnostic radiography.
Reason	Alteration to equipment
Owner	Medical Imaging Department, TCH
Description	Toshiba TSX 101A helical CT scanner with CXXG-008A generator S/Nos. A3522076 (system), A3522715 (generator). Varian CXB-750D Tube Sn. 32875-5Q.
Location	CT Room (Asset number 20854) Medical Imaging Department The Canberra Hospital, Garran
Conditions	Diagnostic radiography.

Reason Address now shows location of practice
Owner Radiation Oncology Department, TCH
Description Phillips model ACQSIM-CT Helical Scanner Simulator S/No 3110 Generator 362250, Tube type CTR1793RGQ S/No 13104 140kVp, 400mA
Location CT Planning Room (3.1.343)
Building 3, Level 1
Radiation Oncology Department
The Canberra Hospital, Garran
Conditions Diagnostic radiography.

Reason Address now shows location of practice
Owner Medical Imaging Department, TCH
Description Diagnostic mobile x-ray machine GE model AMX4 Plus with model 2185226 tube. S/Nos 300060-174003, 2781BC6.
125kVp 320 mAs
Location Mobile radiography unit
Medical Imaging Department
Lvl 2, Building 12, Canberra Hospital
GARRAN ACT 2605
Conditions Diagnostic radiography.

Reason Address now shows location of practice
Owner Stephen K Lising
Description Dental x-ray unit Trophex, S/Nos 82998, 11732 65kVp, 8mA
Location Room 3
Suite 1, 5 McKay Gardens
TURNER ACT 2612
Conditions Diagnostic dental radiography.

Reason Alteration to equipment
Owner Preventive Dental Care Pty Ltd
Description Dental x-ray unit Takara Belmont Co Ltd Acuray model 071A S/Nos 404258, D-88/T10484 70kVp, 10mA
Location Room 3
Suite 6, Deakin Court
Hopetoun Circuit, Deakin
Conditions Diagnostic dental examinations.

Reason Amended conditions to licence
Reason Address now shows location of practice
Owner Dr Newton J Small
Description Diagnostic x-ray unit Universal Uni-master 325/3500 UX 50H 40M S/Nos LM1588- 0981, 65819/77414.
125kVp, 300mA
Location 10 Upper Level
Kambah Shopping Village
Primer Court
KAMBAH ACT 2902
Conditions Diagnostic chiropractic radiography.

Reason	Address now shows location of practice
Owner	Raymond Charles Swanson
Description	Philips Densomat dental x-ray unit, with Oralix-65S tube S/Nos 8620175, 8600549. 65kVp, 7.5mA
Location	Room 1, Suite 3, McKay Gardens Professional Centre McKay Gardens TURNER ACT 2601
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Dept. of Justice & Community Safety
Description	Diagnostic mobile x-ray machine Shimadzu CD x-ray unit Model MC100L 30 S/Nos 62323807, with Circlex tube s/nos 42299-1 & 305. 100kVp, 60mA
Location	Kingston Mortuary Kingston Forensic Medical Centre The Causeway, KINGSTON
Conditions	Forensic radiography.
Reason	Address now shows location of practice
Owner	Raymond Charles Swanson
Description	Dental x-ray unit Phillips Oralix 65S, Densomat S/Nos 8601268, 9124664. 65kVp, 5mA
Location	Room 2, Suite 3, McKay Gardens Professional Centre McKay Gardens TURNER ACT 2601
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Stephen K Lising
Description	Philips Densomat dental x-ray machine with Oralix 65S tube S/Nos 8823896, 8803131. 65kVp, 7.5mA
Location	Room 1 Suite 1, 5 McKay Gardens TURNER ACT 2612
Conditions	Diagnostic dental radiography
Reason	Address now shows location of practice
Owner	Wanniassa Dental Unit Trust
Description	Dental X-ray machine, Philips Secondent E Timer with Oralix 65S tube S/Nos 8823401, 8900397 65kVp, 7.5mA
Location	Room 1 Wanniassa Dental Surgery 48 Rylah Crescent WANNIASSA ACT 2903
Conditions	Diagnostic dental radiography.

Reason	Address now shows location of practice
Owner	Sterling Kitchings
Description	Gendex model Densomat (DET) dental x-ray machine with Oralix 65S tube S/Nos 9420943, 9400996. 65kVp, 7.5mA
Location	Room 2 Suite 9, 1st Floor Gadal Chambers 48 Corinna Street Woden
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Preventive Dental Care Pty Ltd
Description	Glem Image.X System, X-Mind dental x-ray machine with DG-073B tube S/Nos 00006325, 5616 07465094. 70kVp, 8mA
Location	Room 1 Suite 6, Deakin Court Hopetoun Circuit, DEAKIN ACT 2600
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Joseph M Da Cruz
Description	Trophy dental x-ray machine model CCX with model 708 tube S/Nos N809067, 471360. 70kVp, 8mA
Location	Room 1 Dental Surgery Shop 2 Kaleen Shopping Centre Gwydir Place KALEEN ACT 2617
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Atul P Manani
Description	Siemens dental x-ray machine with Siemens Heliodent DS tube S/Nos 04266, 468126 D3302. 60kVp, 7mA
Location	Room 3, Dental Surgeries Ground Floor 39 Murray Crescent MANUKA ACT 2603
Conditions	Diagnostic dental radiography.
Reason	Address now shows location of practice
Owner	Dr Bruce Litchfield
Description	Trophy model Elitys TR-1 dental x-ray machine, S/No 9922J0030, with Trophy TRX 708 tube s/nos XBNG040, 921060 70/60kVp, 4/7mA
Location	Ground Floor Majura Medical Centre Antill & Cowper Streets DICKSON ACT 2602
Conditions	Diagnostic dental radiography.

Reason	Address now shows location of practice
Owner	Dept of Justice & Community Safety
Description	Diagnostic mobile dental x-ray machine Siemens model 4684606D3302 with Heliodont DS tube 60kVp, 7mA S/Nos 4346, 8515
Location	Kingston Mortuary Kingston Forensic Medical Centre The Causeway Kingston
Conditions	Forensic radiography.
Reason	Address now shows location of practice
Owner	Capital Airport Group
Description	Heimann Type HS6040i baggage x-ray machine S/Nos 19035, 47064
Location	Central Screening Point Ground Floor, Common User Terminal Canberra International Airport, CANBERRA AIRPORT ACT 2609
Conditions	Security screening of baggage.
Reason	Address now shows location of practice
Owner	Graeme N Pearce
Description	Diagnostic mobile veterinary x-ray machine Medison model VR1020, S/No 11952 100kVp, 50mAs
Location	Operating Theatre Manuka Veterinary Hospital 85 Flinders Way GRIFFITH ACT 2603
Conditions	Veterinary radiography.
Reason	Address now shows location of practice
Owner	Anita Shroot
Description	Belmont 096-C dental x-ray unit with Belmont D-088 tube. S/Nos C10350, T-91954. 70kVp, 10mA
Location	Unit 7, Room 1, Dental Surgery Dickson Park Professional Centre, 151 Cowper Street DICKSON ACT 2602
Conditions	Diagnostic dental radiography.